HIGHLANDER VDR APT SERVER

HIGHLANDER

homepage | helpdesk | contact

To be the leader in China's Marine Intelligence and Ocean Information Technology Industry.

Notice

VDR B2/S2 APT CPU battery & FAN exchange

Creator: guojb Date:2020-09-28

Dear agent, pls noted recently we found that our model VDR HLD-B2/S2 CPU's Button lithium battery type:BR2032, due to it's dead conduct the VDR SCU and system recording time reset and Unable to actually synchronize with GPS UTC time, This leads to a series of behaviors that recording data anomalies, here we reiterate to all agent that during B2/S2 APT, PLS DO CHANGE THE CPU LITHIUM BATTERY and CPU FAN during the APT job, and also double check again to make sure the VDR system time are synchronize with GPS UTC time while debark, and pls mark above step at your service report, for us to check, if no mentioned above, the COC will be suspend, thanks all your attention. The requirements shall take effect as of the date of this announcement Septembe-28-2020

ICP 06012126 Copyright: Beijing Highlander Digital Technology Co., Ltd.